

## Error description of HAL-Driver `stm32h7xx_hal_fdcan` Version 1.10.0.0

```
HAL_StatusTypeDef HAL_FDCAN_DeactivateNotification(FDCAN_HandleTypeDef *hfdcan, uint32_t InactiveITs)
```

```
{  
    uint32_t ITLineSelection;  
    HAL_FDCAN_StateTypeDef state = hfdcan->State;  
  
    /* Check function parameters */  
    assert_param(IS_FDCAN_IT(InactiveITs));  
  
    if ((state == HAL_FDCAN_STATE_READY) || (state == HAL_FDCAN_STATE_BUSY))  
    {  
        /* Disable the selected interrupts */  
        __HAL_FDCAN_DISABLE_IT(hfdcan, InactiveITs);  
  
        if ((InactiveITs & FDCAN_IT_TX_COMPLETE) != 0U)  
        {  
            /* Disable Tx Buffer Transmission Interrupts */  
            CLEAR_REG(hfdcan->Instance->TXBTIE);  
        }  
  
        if ((InactiveITs & FDCAN_IT_TX_ABORT_COMPLETE) != 0U)  
        {  
            /* Disable Tx Buffer Cancellation Finished Interrupt */  
            CLEAR_REG(hfdcan->Instance->TXBCIE);  
        }  
    }  
}
```

**// The following highlighted code block (→ reset of the ILE register) should be removed here and // are not needed!**

```
// Deactivating of the interrupt in the IE register is sufficient.
// At the moment this lines here in this function can cause a configuration error in the
// ILE register.
// A interrupt line flag in the ILE register can be cleared wrongly even one another active
// interrupt is connected to this interrupt line !
// A call of the function HAL_FDCAN_ActivateNotification doesn't set the wrongly cleared
// interrupt line flag before !
//
// If someone doesn't know about this error, someone will be wondering why the wanted
// interrupt will never occur !
//
// Workaround example for TX-COMplete interrupt:
// Calling of the macro CLEAR_BIT(hfdcan->Instance->IE, FDCAN_IT_TX_COMPLETE) instead of
// the function HAL_FDCAN_DeactivateNotification at the moment.
```

```
ITLineSelection = hfdcan->Instance->ILS;

if ((hfdcan->Instance->IE | ITLineSelection) == ITLineSelection)
{
    /* Disable Interrupt line 0 */
    CLEAR_BIT(hfdcan->Instance->ILE, FDCAN_INTERRUPT_LINE0);
}

if ((hfdcan->Instance->IE & ITLineSelection) == 0U)
{
    /* Disable Interrupt line 1 */
}
```

```

    CLEAR_BIT(hfdcan->Instance->ILE, FDCAN_INTERRUPT_LINE1);
}

/* Return function status */
return HAL_OK;
}
else
{
    /* Update error code */
    hfdcan->ErrorCode |= HAL_FDCAN_ERROR_NOT_INITIALIZED;

    return HAL_ERROR;
}
}

```

**HAL\_StatusTypeDef HAL\_FDCAN\_ActivateNotification(FDCAN\_HandleTypeDef \*hfdcan, uint32\_t ActiveITs, uint32\_t BufferIndexes)**

```

{
    HAL_FDCAN_StateTypeDef state = hfdcan->State;

    /* Check function parameters */
    assert_param(IS_FDCAN_IT(ActiveITs));

    if ((state == HAL_FDCAN_STATE_READY) || (state == HAL_FDCAN_STATE_BUSY))
    {
        // The following highlighted code block (→ setting of the ILE register) should be moved into the
        // function HAL_FDCAN_ConfigInterruptLines,
        // because the interrupt lines will be configured there (→ setting of the ILS register).
        // At the moment the lines here in this function can cause a configuration error in the
    }
}

```

```
// ILE register, if this function is called first,  
// before function HAL_FDCAN_ConfigInterruptLines was called.  
//  
// If someone doesn't know the right sequence of calling of the HAL-driver functions,  
// someone will be wondering why the wanted interrupt will never occur !
```

```
/* Enable Interrupt lines */  
if ((ActiveITs & hfdcan->Instance->ILS) == 0U)  
{  
    /* Enable Interrupt line 0 */  
    SET_BIT(hfdcan->Instance->ILE, FDCAN_INTERRUPT_LINE0);  
}  
else if ((ActiveITs & hfdcan->Instance->ILS) == ActiveITs)  
{  
    /* Enable Interrupt line 1 */  
    SET_BIT(hfdcan->Instance->ILE, FDCAN_INTERRUPT_LINE1);  
}  
else  
{  
    /* Enable Interrupt lines 0 and 1 */  
    hfdcan->Instance->ILE = (FDCAN_INTERRUPT_LINE0 | FDCAN_INTERRUPT_LINE1);  
}  
  
if ((ActiveITs & FDCAN_IT_TX_COMPLETE) != 0U)  
{  
    /* Enable Tx Buffer Transmission Interrupt to set TC flag in IR register,  
    but interrupt will only occur if TC is enabled in IE register */  
    SET_BIT(hfdcan->Instance->TXBTIE, BufferIndexes);  
}  
  
if ((ActiveITs & FDCAN_IT_TX_ABORT_COMPLETE) != 0U)  
{
```

```
/* Enable Tx Buffer Cancellation Finished Interrupt to set TCF flag in IR register,  
   but interrupt will only occur if TCF is enabled in IE register */  
SET_BIT(hfdcan->Instance->TXBCIE, BufferIndexes);  
}  
  
/* Enable the selected interrupts */  
__HAL_FDCAN_ENABLE_IT(hfdcan, ActiveITs);  
  
/* Return function status */  
return HAL_OK;  
}  
else  
{  
/* Update error code */  
hfdcan->ErrorCode |= HAL_FDCAN_ERROR_NOT_INITIALIZED;  
  
return HAL_ERROR;  
}  
}
```

```

HAL_StatusTypeDef HAL_FDCAN_ConfigInterruptLines(FDCAN_HandleTypeDef *hfdcan, uint32_t ITList, uint32_t
InterruptLine)
{
    HAL_FDCAN_StateTypeDef state = hfdcan->State;

    /* Check function parameters */
    assert_param(IS_FDCAN_IT(ITList));
    assert_param(IS_FDCAN_IT_LINE(InterruptLine));

    if ((state == HAL_FDCAN_STATE_READY) || (state == HAL_FDCAN_STATE_BUSY))
    {
        // The following highlighted code block (→ setting of the ILE register) should be inserted here
        // instead in the function HAL_FDCAN_ActivateNotification,
        // because the interrupt lines will be configured here (→ setting of the ILS register).
        // At the moment this lines are present in function HAL_FDCAN_ActivateNotification.
        // It can cause a configuration error in the ILE register, if this function is called after the function
        // HAL_FDCAN_ActivateNotification.
        //
        // If someone doesn't know the right sequence of calling of the HAL-driver functions, someone
        // will be wondering why the wanted interrupt will never occur !

        /* Assign list of interrupts to the selected line */
        if (InterruptLine == FDCAN_INTERRUPT_LINE0)
        {
            CLEAR_BIT(hfdcan->Instance->ILS, ITList);
            SET_BIT(hfdcan->Instance->ILE, FDCAN_INTERRUPT_LINE0);
        }
        else /* InterruptLine == FDCAN_INTERRUPT_LINE1 */
        {

```

```

SET_BIT(hfdcan->Instance->ILS, ITList);
SET_BIT(hfdcan->Instance->ILE, FDCAN_INTERRUPT_LINE1);
}

/* Return function status */
return HAL_OK;
}
else
{
/* Update error code */
hfdcan->ErrorCode |= HAL_FDCAN_ERROR_NOT_INITIALIZED;

return HAL_ERROR;
}
}

```

```

HAL_StatusTypeDef HAL_FDCAN_TT_DeactivateNotification(FDCAN_HandleTypeDef *hfdcan, uint32_t InactiveTTITs)
{
uint32_t ITLineSelection;
HAL_FDCAN_StateTypeDef state = hfdcan->State;

/* Check function parameters */
assert_param(IS_FDCAN_TT_INSTANCE(hfdcan->Instance));
assert_param(IS_FDCAN_TT_IT(InactiveTTITs));

if ((state == HAL_FDCAN_STATE_READY) || (state == HAL_FDCAN_STATE_BUSY))
{
/* Disable the selected TT interrupts */
__HAL_FDCAN_TT_DISABLE_IT(hfdcan, InactiveTTITs);
}
}

```

```
// The following highlighted code block (→ reset of the ILE register) should be removed here and  
// are not needed!  
// Deactivating of the interrupt in the TTIE register is sufficient.  
// At the moment this lines here in this function can cause a configuration error in the  
// ILE register.  
// A interrupt line flag in the ILE register can be cleared wrongly even one another active  
// interrupt is connected to this interrupt line !  
// A call of the function HAL_FDCAN_TT_ActivateNotification doesn't set the wrongly cleared  
// interrupt line flag before !  
//  
// If someone doesn't know about this error, someone will be wondering why the wanted  
// interrupt will never occur !  
//  
// Workaround example for REGISTER TIMEMARK interrupt:  
// Calling of the macro CLEAR_BIT(hfdcan->tcan->TTIE, FDCAN_TT_IT_REG_TIME_MARK);  
// instead of the function HAL_FDCAN_TT_DeactivateNotification at the moment.
```

```
ITLineSelection = hfdcan->tcan->TTILS;
```

```
if ((hfdcan->tcan->TTIE | ITLineSelection) == ITLineSelection)  
{  
    /* Disable Interrupt line 0 */  
    CLEAR_BIT(hfdcan->Instance->ILE, FDCAN_INTERRUPT_LINE0);  
}
```



```
if ((hfdcan->tcan->TTIE & ITLineSelection) == 0U)
{
    /* Disable Interrupt line 1 */
    CLEAR_BIT(hfdcan->Instance->ILE, FDCAN_INTERRUPT_LINE1);
}

/* Return function status */
return HAL_OK;
}
else
{
    /* Update error code */
    hfdcan->ErrorCode |= HAL_FDCAN_ERROR_NOT_INITIALIZED;

    return HAL_ERROR;
}
}
```

```

HAL_StatusTypeDef HAL_FDCAN_TT_ActivateNotification(FDCAN_HandleTypeDef *hfdcan, uint32_t ActiveTTITs)
{
    HAL_FDCAN_StateTypeDef state = hfdcan->State;

    /* Check function parameters */
    assert_param(IS_FDCAN_TT_INSTANCE(hfdcan->Instance));
    assert_param(IS_FDCAN_TT_IT(ActiveTTITs));

    if ((state == HAL_FDCAN_STATE_READY) || (state == HAL_FDCAN_STATE_BUSY))
    {
        // The following highlighted code block (→ setting of the ILE register) should be moved into the
        // function HAL_FDCAN_TT_ConfigInterruptLines,
        // because the interrupt lines will be configured there (→ setting of the TTILS register).
        // At the moment the lines here in this function can cause a configuration error in the
        // ILE register, if this function is called first,
        // before function HAL_FDCAN_TT_ConfigInterruptLines was called.
        //
        // If someone doesn't know the right sequence of calling of the HAL-driver functions, someone
        // will be wondering why the wanted interrupt will never occur !

        /* Enable Interrupt lines */
        if ((ActiveTTITs & hfdcan->ttcan->TTILS) == 0U)
        {
            /* Enable Interrupt line 0 */
            SET_BIT(hfdcan->Instance->ILE, FDCAN_INTERRUPT_LINE0);
        }
        else if ((ActiveTTITs & hfdcan->ttcan->TTILS) == ActiveTTITs)
        {
            /* Enable Interrupt line 1 */

```

```
    SET_BIT(hfdcan->Instance->ILE, FDCAN_INTERRUPT_LINE1);
}
else
{
    /* Enable Interrupt lines 0 and 1 */
    hfdcan->Instance->ILE = (FDCAN_INTERRUPT_LINE0 | FDCAN_INTERRUPT_LINE1);
}

/* Enable the selected TT interrupts */
__HAL_FDCAN_TT_ENABLE_IT(hfdcan, ActiveTTITs);

/* Return function status */
return HAL_OK;
}
else
{
    /* Update error code */
    hfdcan->ErrorCode |= HAL_FDCAN_ERROR_NOT_INITIALIZED;

    return HAL_ERROR;
}
}
```

```

HAL_StatusTypeDef HAL_FDCAN_TT_ConfigInterruptLines(FDCAN_HandleTypeDef *hfdcan, uint32_t TTITList, uint32_t
InterruptLine)
{
    HAL_FDCAN_StateTypeDef state = hfdcan->State;

    /* Check function parameters */
    assert_param(IS_FDCAN_TT_INSTANCE(hfdcan->Instance));
    assert_param(IS_FDCAN_TT_IT(TTITList));
    assert_param(IS_FDCAN_IT_LINE(InterruptLine));

    if ((state == HAL_FDCAN_STATE_READY) || (state == HAL_FDCAN_STATE_BUSY))
    {
        // The following highlighted code block (→ setting of the ILE register) should be inserted here
        // instead in the function HAL_FDCAN_TT_ActivateNotification,
        // because the interrupt lines will be configured here (→ setting of the TTILS register).
        // At the moment this lines are present in function HAL_FDCAN_TT_ActivateNotification.
        // It can cause a configuration error in the ILE register, if this function is called after the function
        // HAL_FDCAN_ActivateNotification.
        //
        // If someone doesn't know the right sequence of calling of the HAL-driver functions, someone
        // will be wondering why the wanted interrupt will never occur !

        /* Assign list of interrupts to the selected line */
        if (InterruptLine == FDCAN_INTERRUPT_LINE0)
        {
            CLEAR_BIT(hfdcan->ttcan->TTILS, TTITList);
            SET_BIT(hfdcan->Instance->ILE, FDCAN_INTERRUPT_LINE0);
        }
    }
}

```

```
else /* InterruptLine == FDCAN_INTERRUPT_LINE1 */
{
    SET_BIT(hfdcan->tcan->TTILS, TTITList);
    SET_BIT(hfdcan->Instance->ILE, FDCAN_INTERRUPT_LINE1);
}

/* Return function status */
return HAL_OK;
}
else
{
    /* Update error code */
    hfdcan->ErrorCode |= HAL_FDCAN_ERROR_NOT_INITIALIZED;

    return HAL_ERROR;
}
}
```

2022-01-20, GK\_CPfal2020