





Does anyone have any ideas on why this is happening, and how to get out of a sticky situation like this? How can I detect that this has even happened on the STM?

I'm using STM32Cube FW\_F3 V1.9.0